


Priorities for modifying Preshower LV connectors - January 2016

Priorities:

- 1** Heating
- 2** Known problems
- 3** Suspicious
- 4** Remainder




VIEW TOWARDS PRESHOWER & ECAL ENDCAP

ES-

Priorities:

- 1** Heating
- 2** Known problems
- 3** Suspicious
- 4** Remainder



VIEW TOWARDS PRESHOWER & ECAL ENDCAP